

FIG. 1




FIG. 1A







FIG. 2




Temperature FIG. 3




Phases, Position #10 FIG. 4




In-Plain Strains, Position #10 FIG. 5




In-Plane Stress FIG. 6




Temperature FIG. 7







In-Plane Stress FIG. 11




Temperature FIG. 12




Phases, Position #1 FIG. 13



Phases, Position #1 FIG. 14



In-Plain Strains, Position #1 FIG. 15



In-Plane Stress FIG. 16

## WARPAGE IN 0.001 INCH FOR STEADY-STATE TEMP = 280° C




FIG. 17

## WARPAGE IN 0.001 INCH FOR STEADY-STATE TEMP = 320° C





FIG. 18



WARPAGE ( OUT OF FLATNESS ) OF SPRAYED METALLIC PLATE VS. STEADY STATE SPRAY TEMPERATURE FIG. 19